

Model: AUSTIN GRAY 40X80(A)

Codes: 100202047 - V57100041

Water absorption: Bla - Porcelánico (E<=0.1%)



**DIMENSIONAL FEATURES**  
UNE-EN ISO 10545-2

Length	800 MM	
Length and width deviation	Below 0.15%	+/-0.3%*
Side straightness deviation	Below 0.15%	+/-0.3%*
Squareness deviation	Below 0.15%	+/-0.3%*
Surface flatness deviation	Below 0.15%	+/-0.4%*
Thickness	10.5 MM	+/-5%*
Width	400 MM	

\*ISO-13006:2018 UNE-EN 14411:2016

**MECHANICAL FEATURES**  
UNE-EN ISO 10545-4-6-7-11

Abrasion resistance	PEI 3 / 600v	
Breaking strength	3118 N	>1300N*
Crazing resistance	Resists 3 cycles	
Modulus of rupture	54 N/MM2	>=35N/mm2*

\*ISO-13006:2018 UNE-EN 14411:2016

**HYGIENIC FEATURES**  
UNE-EN ISO 10545-13-14:1995

Chemical resistance	Class "A" for swimming pools and cleaning products (resists attack). Minimum Class "B" for acids and bases	B Min.*
Stain resistance	Class 5. Easy cleaning with water	3 Min.*

\*ISO-13006:2018 UNE-EN 14411:2016

**SCOPE OF USE**

Technical code-1	Use on medium traffic floors	
------------------	------------------------------	--

**ANTI-SLIP VALUE**  
UNE 41901:2017 EX, UNE 41902:2017 EX, DIN-51130 y ASTM C1028

4s	18	
Dynamic coefficient of friction	0.34	
Slip resistance (pendulum-wet)	CL1	
Slip resistance (ramp)	R-10	

\*ISO-13006:2018 UNE-EN 14411:2016

System Certification



V57100041  
100202047

AUSTIN GRAY

**PORCELANOSA**  
PORCELANOSA Grupo

**PACKING**

Boxes	1.28 M2/BOX	
Pallets	61.44 M2/PAL	
Units	0.32 M2/PIECE	

System Certification



Do not use cleaning agents containing hydrofluoric acid.  
It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint.  
For big sizes, it is recommended to fix with mortars containing polymeric additives and to use the double glueing technique.  
Mosaic tiles must be grouted.  
This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.