

Model: EWOOD CAMEL NAT.(22PZS/PAL) 120X250 (A) Codes: 100274565 - C229803551 Absorption: Bla - Porcelanico (E<=0.1%) Family: EWOOD Tone variations: V3 Finish: NORMAL





DIMENSIONAL FEATURES UNE-EN ISO 10545-2				
Length	2500 MM			
Length and width deviation	Below 0.20%	+/-0.3%*		
Side straightness deviation	Below 0.15%	+/-0.3%*		
Squareness deviation	Below 0.20%	+/-0.3%*		
Surface flatness deviation	Below 0.20%	+/-0.4%*		
Thickness	6 MM			
Width	1200 MM			
*ISO-13006:2015 UNE-EN 14411:2017				

MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11			
Abrasion resistance	<140		
Breaking strenght	>1100 N		
Modulus of rupture	>40 N/MM2		
*ISO-13006:2015 UNE-EN 14411:2017			

	HYGIENIC FEATURES UNE-EN ISO 10545-13-14	
Chemical resistance	CLASE A	
Climate shock test. resistance index	RESISTE	
Resistance to cold food products	APTO	
Stain resistance	5	
*ISO-13006:2015 UNE-EN 14411:2017		

	ANTI-SLIP VALUE CEN/TS 41901/02, DIN-51130 y ASTM A137.1
4s	DRY>36-LOW WET>24-MODERATE
Slip resistance (pendulum-wet)	CL1
Slip resistance (ramp)	R9A
Stain resistance	5
*ISO-13006:2015 UNE-EN 14411:2017	

SCOPE OF USE

Technical code-1 Technical code-2 Use on walls Dry interior floors



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by URBATEK S.A. In its polished finish, due to high gloss, light reflection can create optical effects that resemble stains. In no case they do not comply with the ISO 13006 product standard. Being the ceramic material that most resembles natural stone, it can show slight variations in shade, color spots and vein among pieces. #Refer to section 4 of the support document DB/SUA 3. This material can be installed in public, dry areas with a slope under 6% (it gets the same classification as a Class 1 according to wet pendulum).



PACKING			
Boxes	1 PIECES/BOX		
Pallets	22 PIECES/PAL		
Units	1 PIECES		



19/09/2021

Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by URBATEK S.A. In its polished finish, due to high gloss, light reflection can create optical effects that resemble stains. In no case they do not comply with the ISO 13006 product standard. Being the ceramic material that most resembles natural stone, it can show slight variations in shade, color spots and vein among pieces. #Refer to section 4 of the support document DB/SUA 3. This material can be installed in public, dry areas with a slope under 6% (it gets the same classification as a Class 1 according to wet pendulum).